

CYCLEMASTER® 3Way Ball Valve
BRAZING INSTRUCTIONS

Ambient Temp. -40° to 175° F
 Operating Media Temp. -40° to 300° F
TS -40° to 149° C

Max. Temp. 1300° F
TS 700° C

Max. Temp. 300° F
TS 150° C

Stem position when brazing

Flow Tailpiece Flow Body

Note: Purge with nitrogen during brazing.

FORMS: INST-040
10/19

Loosen Nut

Change Stem Direction

Hand Tighten

Tighten 1/4 Turn

Ball Valve MUST be in FULL OPEN or FULL CLOSED POSITION

FORMS: INST-040
10/19

CYCLEMASTER® 3 Way Ball Valve
BRAZING INSTRUCTIONS

Ambient Temp. -40° to 175° F
 Operating Media Temp. -40° to 300° F
TS -40° to 149° C

Max. Temp. 1300° F
TS 700° C

Max. Temp. 300° F
TS 150° C

Stem position when brazing

Flow Tailpiece Flow Body

Note: Purge with nitrogen during brazing.

FORMS: INST-040
10/19

Loosen Nut

Change Stem Direction

Hand Tighten

Tighten 1/4 Turn

Ball Valve MUST be in FULL OPEN or FULL CLOSED POSITION

FORMS: INST-040
10/19