





CYCLEMASTER® Ball Valve BRAZING INSTRUCTIONS

CFC, HCFC & HFC


Ambient
-40° to 175° F
-40° to 79° C

Operating Media
-40° to 300° F
-40° to 149° C

MWP = 700 psig
48 Bar




OPEN Position




CLOSED Position


CFC, HCFC & HFC




Loosen Nut




Change Stem
Direction



Hand Tighten



Tighten 1/4 Turn



**Ball Valve MUST be in FULL OPEN
or FULL CLOSED POSITION**