


# M<sup>®</sup> MCC INLINE STRAINER INSTALLATION INSTRUCTIONS

## CFC, HCFC & HFC

Ambient  
-60 → +175° F  
-51 → +79° C

Operating Media  
-40 → +300° F  
-40 → +149° C



Medium temperature (500° F, 260° C) solder is preferred

### Notes:

1. Ensure application does not exceed pressure stamped on product.
2. Compatible with fluorinated refrigerants.


FORM: INST-006  
12/05

# M<sup>®</sup> MCC INLINE STRAINER INSTALLATION INSTRUCTIONS

## CFC, HCFC & HFC

Ambient  
-60 → +175° F  
-51 → +79° C

Operating Media  
-40 → +300° F  
-40 → +149° C



Medium temperature (500° F, 260° C) solder is preferred

### Notes:

1. Ensure application does not exceed pressure stamped on product.
2. Compatible with fluorinated refrigerants.


FORM: INST-006  
12/05

# M<sup>®</sup> MCC INLINE STRAINER INSTALLATION INSTRUCTIONS

## CFC, HCFC & HFC

Ambient  
-60 → +175° F  
-51 → +79° C

Operating Media  
-40 → +300° F  
-40 → +149° C



Medium temperature (500° F, 260° C) solder is preferred

### Notes:

1. Ensure application does not exceed pressure stamped on product.
2. Compatible with fluorinated refrigerants.


FORM: INST-006  
12/05

# M<sup>®</sup> MCC INLINE STRAINER INSTALLATION INSTRUCTIONS

## CFC, HCFC & HFC

Ambient  
-60 → +175° F  
-51 → +79° C

Operating Media  
-40 → +300° F  
-40 → +149° C



Medium temperature (500° F, 260° C) solder is preferred

### Notes:

1. Ensure application does not exceed pressure stamped on product.
2. Compatible with fluorinated refrigerants.

FORM: INST-006  
12/05