

RoHS III (Directive (EU) 2015/863 of 4 June 2015)

Status Update: 7 April 2023

Mueller Refrigeration, LLC is pleased to announce that the following product lines are in conformance with the RoHS III Directive (EU) 2015/863 of 4 June 2015 and formerly met the requirements of Directives 2011/65/EU and 2002/95/EU since its implementation:

Ball Valves	Four Bolt Check Valves
Brass Check Valves	Gaskets
Brass Compressor Valves	LEXVIII
Cast Iron Compressor Valves	Machined Brass & Copper Fittings
Copper Tubes	Magnetic Check Valves
Diaphragm Valves	Moisture Indicators
Ejector Valve	Packed Angle Valves
EXVIII	Pressure Relief Valves
Filter Driers	Screw Bonnet Check Valves
Forged Brass Flanges	Suction Service Valves
Forged Brass Nuts	Y Strainers

As permitted by the Directive, Mueller Refrigeration, LLC self-certifies to Directive (EU) 2015/863. The product lines that do not comply with the RoHS standard (due to high content of RoHS restricted metals) but will not function properly without the use of these metals are believed to fall within Paragraph 18 of the Directive: “Exemptions from the substitution requirement should be permitted if substitution is not possible from the scientific and technical point of view, taking specific account of the situation of SMEs or if the negative environmental, health and consumer safety impacts caused by substitution are likely to outweigh the environmental, health and consumer safety benefits of the substitution or the reliability of substitutes is not ensured. The decision on exemptions and on the duration of possible exemptions should take into account the availability of substitutes and the socioeconomic impact of substitution. Life-cycle thinking on the overall impacts of exemptions should apply, where relevant. Substitution of the hazardous substances in EEE should also be carried out in such a way as to be compatible with the health and safety of users of EEE.” The products listed above fall under the exemption Annex III Section 6(c).

For additional information regarding product compliance with RoHS Directive, please contact your local sales representative.