



RoHS II (Directive 2011/65/EU of 8 June 2011)

Status Update: June 11, 2014

Mueller Refrigeration, LLC is pleased to announce that the following product lines are in conformance with the RoHS II Directive:

- | | |
|-----------------------------|----------------------------------|
| Ball Valves | Gaskets |
| Brass Check Valves | LXVIII |
| Brass Compressor Valves | Machined Brass & Copper Fittings |
| Cast Iron Compressor Valves | Magnetic Check Valves |
| Copper Tubes | Moisture Indicators |
| Diaphragm Valves | Packed Angle Valves |
| EXVIII | Pressure Relief Valves |
| Filter Driers | Screw Bonnet Check Valves |
| Forged Brass Flanges | Suction Service Valves |
| Forged Brass Nuts | Y Strainers |
| Four Bolt Check Valves | |

Mueller Refrigeration, LLC product lines that do not comply with the RoHS standard (due to high content of RoHS restricted metals) but will not function properly without the use of these metals are believed to fall within Paragraph 18 of the Directive: “Exemptions from the substitution requirement should be permitted if substitution is not possible from the scientific and technical point of view, taking specific account of the situation of SMEs or if the negative environmental, health and consumer safety impacts caused by substitution are likely to outweigh the environmental, health and consumer safety benefits of the substitution or the reliability of substitutes is not ensured. The decision on exemptions and on the duration of possible exemptions should take into account the availability of substitutes and the socioeconomic impact of substitution. Life-cycle thinking on the overall impacts of exemptions should apply, where relevant. Substitution of the hazardous substances in EEE should also be carried out in such a way as to be compatible with the health and safety of users of EEE.” It is the responsibility of the end user to ensure that the products do in fact fall under the exemption.

| <u>Product Line</u> | <u>Reason for Noncompliance</u> | <u>Corrective Action</u> |
|---------------------|---|--------------------------|
| Fusible Plugs | Fusible alloy above limit for lead and/or cadmium | No substitute available |

For additional information regarding product compliance with RoHS Directive, please contact your local sales representative, or Mueller Refrigeration’s Customer Service department at 800-251-8991 or (615) 374-2124.