



345 Carlingview Drive
Toronto, Ontario
CANADA M9W 6N9
Tel.: 416.734.3300
Fax.: 416.231.1626
Toll Free: 1.877.682.8772
www.tssa.org

October 16, 2017

RALPH DAVIS
MUELLER REFRIGERATION LLC
121 ROGERS ST
HARTSVILLE TN 37074
US

Service Request Type.: BPV-National CSA
Service Request No.: 2098702
Your Reference No.:
Registered to.: MUELLER REFRIGERATION LLC

Dear RALPH DAVIS,

Please find enclosed the original response from QC, SK registered under the CRN No.:
CSA-0G0314.96R6.

As all jurisdictional fees are handled by the Technical Standards and Safety Authority (TSSA), you do not pay any jurisdictions directly.

Should you have any questions or require further assistance, I will be happy to assist you.
For general enquiries, please contact a Customer Service Advisor at 1.877.682.TSSA (8772) or e-mail customerservices@tssa.org. When contacting TSSA regarding this file, please refer to the Service Request number provided above.

Yours truly,

Joanna Karpinski
Tel: 416-734-3377
Fax: 416-231-6183
Email: jkarpinski@tssa.org



To:	TSSA	From:	Janet Townsend
Company:	Mueller Refrigeration LLC	Phone:	416-747-4291
Pages:	11	Location:	Toronto
Our File:	ANR-4610	Date:	August 22, 2017

Your File: 2098702

Subject: Request for Design Registration

Dear Ms. Francis,

CSA has reviewed the documentation submitted by TSSA on behalf of Mueller Refrigeration LLC.

These fittings have been registered by CSA for the Province of Québec. In accordance with an agreement between CSA, the Provinces of Québec and Saskatchewan; this registration is recognized by Québec and Saskatchewan. These fittings are acceptable for use in these Provinces.

The letters CSA will be applied as a prefix to the CRN indicate which fittings have been registered in this manner. A copy of the stamped Statutory Declaration is attached.

The CRN is CSA-0G0314.96R6.

A copy of the Statutory Declaration with an original stamp affixed will be forwarded to you along with our invoice by regular mail.

Yours truly,

A handwritten signature in blue ink that reads 'Janet Townsend'.

Janet Townsend
Program Manager
CSA Group

178 Rexdale Blvd.
Toronto, ON, M9W 1R3


**CERTIFIED
TRUE COPY**
Date: Mar 29/17
Signature: [Handwritten Signature]

Colleen Anne Ratcliff
a Commissioner, etc. City of Toronto, for the
Technical Standards & Safety Authority
Expires July 24, 2019

REGISTERED
CRN: 060314.96R6
Registration Process administered by
CSA Group per CSA B51

REGISTERED 
CRN: CSA-060314.96R6
Registration Process administered by
CSA Group per CSA B51

Technical Review performed per CSA B51
Performed by: ANRIC Enterprises Inc.
Signed: [Handwritten Signature: Paul Bames]
Date: August 19, 2017

ACI Central Inc.

20 McAulay Court
 Charlottetown, PE C1A 9M7
 Canada

Detail Information - Revision - Pressure Fitting Design

CRN: OG0314.9870YTN REV9

Manufacturer: Mueller Refrigeration Company LLC

FID/PV: FID-455

Trademark: stylized and wide blocked font "M" with an upside down triangle shape above.

Description: Rev. is CRN renewal. Safety relief valves incl. A-15501, A-15508, A-15509, B-34067, A-15502, A-15503, A-15512, B-33755, B-34425, A-15513, A-17430, A-18774, B-33746, B-33752, B-33753, B-33754, A-15504, A-15514, B-35413, A-18736, A-18737, A-18762, A-18783, A-18784, A-15506, B-34444, A-17840. (There are 45 models/part numbers - see 'Product scope').

Design code: ASME Sec.VIII, Div.1

Registration date: 03/06/2017

Expiry date: 03/03/2027

Pressure Rating	Type	Size	Material
160-450psig	A-15501, A-15508, A-15509, B-34067 (Gas)	1/8" to 1/2" (inlet)	B16 C36000
150-700psig	A-15502, A-15503, A-15512 (Gas) B-33755, B-34425, A-15513	1/8"-3/8"(in); 3/8", 1/2"(out) A-17430, A-18774, B-33746,	B16 C36000 B-33752, B-33753, B-33754
150-700psig	A-15504, A-15514, B-35413, A-18736, A-18737, A-18762, (Gas)	3/8"-7/8"(in); 5/8", 3/4"(out) A-18783, A-18784	B16 C36000
150-450psig	A-15506, B-34444 (gas)	3/4"-7/8"(in.); 3/4"(top)	B16 C36000
150-450psig	A-17840, A-18735, B-34519 (gas)	3/4"-1.625"(in.); 1"(out)	B16 C36000
150-450psig	A17834, B34580, A18387, A18473	1-1.625"(inlet); 1", 1.25"(outlet)	B16 C36000

There are several part numbers

which are not shown above

but are included with this

registration due to limited space

