

CERTIFICATE OF COMPLIANCE

Certificate Number 20181120-SA778
Report Reference SA778-19390116
Issue Date 2018-NOVEMBER-20

Issued to: MUELLER REFRIGERATION L L C
121 ROGERS ST
HARTSVILLE TN 37074

**This certificate confirms that
representative samples of**

FUSIBLE PLUGS, REFRIGERANT
Fusible plugs, refrigerant, Part No. A-14017 through A-14019, A-14021 through 14027, A-14050, A-14058 through 14060, A-14062 through 14064, A-15214, A-19065, A-19066, B-32490, B-32729, B-33345, B-33573, B-33574, B-33575, B-33604, B-33811, B-33812, B-33824, B-34048, B-34053, B-34558, B-35584.

Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 207, Refrigerant-Containing Components and Accessories, Nonelectrical
CSA C22.2 No. 140.3-15, Refrigerant-Containing Components for use in Electric Equipment

Additional Information: See the UL Online Certifications Directory at <https://iq.ulprospector.com> for additional information.

This *Certificate of Compliance* does not provide authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

